Global Air Traffic Management (GATM)



Capt Gina Hubbard Feb 2000

OVERVIEW


- GATM Defined
- Operational Significance
- AFMSS Implementation Plans

GATM (Air Force CNS/ATM)

Category	Components	Goal
Communication Digital Radios to Handle Reduced Channel Spacing and Datalink	8.33 KHzRadiosCPDL	Air Traffic Management Transition from ATC to ATM With the Ultimate Goal of Free Flight (2010)
Navigation Better Horizontal/Vertical PositionAccuracy to Enable Reduced Separation	· RNP • RVSM • FM Immunity	
Surveillance Enhanced Situational Awareness, Collision Avoidance, Automatic Position Reporting	ADS-B/AMode STCAS	

GATM=Continued Operation IAW New Separation Standards/Procedures

GATM Airspace by 2003-05



2005... "Non-Compliant" Platform Tasked to Deploy to Europe

- Trans-Oceanic Impacts: Cross Below FL 290 (Reduced Vertical Separation Minimum - RVSM)
- Possible In-Theater GATM Impacts
 - Restricted from VOR or ILS Approach (FM Immunity)
 - Airspace Access Restricted (FM Immunity, ACAS/TCAS)
 - Restricted Ops to Below FL 245 (8.33 VHF)
 - Unable to Fly General Air Traffic (Mode S)... Operational Air Traffic may still be allowed

German Announcement

"State aircraft or others without properly protected ILS/VOR receivers...cannot expect to use such equipment for instrument approaches to German aerodromes after 1 January 2001."


GATM Example: Aircraft Separation by 2003

Aircraft Separation Decreases Over Time

2000' to 1000' Vertically

60 to 30 NM Horizontally

Future




Present

RVSM Mar 1997 **CNS/ATM** 2003

New
Communication,
Navigation and
Surveillance
Equipment Is
Needed to
Preserve Safety
and Efficiency

Past

Impact Of Noncompliance



IT'S HAPPENING NOW!

- Guard Lift KC-135 Mission to Aviano AFB
 - Not RVSM compliant
 - » Transoceanic flight restricted to FL 290 and below
 - Radios not 8.33KHz compliant
 - » Parisian Sector Controller would not allow SRS exempt aircraft into their airspace
- ALLIED FORCE B-2 Mission to Kosovo
 - Not RVSM compliant
 - » Transoceanic flight restricted FL 290 and below
 - » Weather a SIGNIFICANT factor

BOTTOM LINE: Non-compliance = Less Than Optimum Routing = More Time + More Fuel

Where Is Mission Planning?

TODAY

- MPS
 - » Impact not evaluated yet
- PFPS
 - » Changes being incorporated into AWEs for TASM aircraft (C-17, C-141, C-5, KC-10, KC-135, C-9, E-3, E-8)
 - » Other platform's impacts not evaluated yet
- JMPS
 - » Working to add to Version 1 requirements
- NEAR TERM
 - AFMSS GATM Tiger Team established Jan 00
 - Jul 00 present Operational Impact Analysis (OIA)
- FAR TERM
 - Permanent AFMSS GATM IPT

GATM POCS

HQ AMC

Maj Daryl Taylor 6459

DSN 576-

HQ ACC

Maj Brian Howell (Aircraft Reqmts) DSN 574-

1077

Mr Fred Aronson (Mission Planning) DSN 574-

1868

LtC Robert Clardy (Ops Issues) DSN 574-

5896

ESC/ACU

Capt Gina Hubbard 1186 x4637

DSN 478-